

16584

Dec. 7 1883

REPAIRS

Present Condition of the

General Observations and Opinion.

The Amount of Fee.....£ 2 : ____ : ____ is received by me,

Special..... 2 : 2 :

Certificate (if required) : /0:

Committee's Minute

Character assigned

Specimen to
examined upon 5. 52 20

Lloyd's Register
Foundation

629-0441

16584 Lem

Yellow Metal - about 200 feet of new water of 8 inch. Some new
planks stated to have been put in the upper course (now done
over) and also a new stroke all round. The berthing of the
Poop Sheathed with $1\frac{1}{2}$ inch teak fitted under. New stay knee
to the front beam of poop. Two Stoper knees to the top
Gallant forecastle. New waterway plank sheer and plank
of the deck next sheete on the poop. ²⁵⁵ New Head with
Hawse pipes & blocks ship caulked all over - new
partners around the Mast

Jourleson



© 2019

Lloyd's Register
Foundation