

ANNUAL SURVEYS.

16604

No. 99 on the *Belle Alliance* Survey held at *London* Date *13th Dec^r* 1850
 Master *Stephens*
 Tonnage *677* Built at *Bengal* When built *1817*
 By whom built *Stephens* Owners *Somers Brothers*
 Port belonging to *London* Destined Voyage *Mediterranean*
 If Surveyed Afloat or in Dry Dock

Last Survey, No. *1553* Port of *London* Classed *A. 1*
SS 1849

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <i>ym</i> When put on <i>Dec^r</i>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

at present bottom stripped, caulked from the keel to the tops of the wales. Kulsams and hooding cups tested and sheathed with yellow metal on the doubling.
 Committee Minute *118th Feb^y* 1851
 Character assigned *A. 1* *Ship is in efficient condition and is fit to remain as classed*
 Certificate (if required)

No. *835* Survey held at *London* Date *4th* *Jan^y* 1851
 on the *Ship "Madagascar"* Master
 Tonnage *957* Built at *London* When built *1837*
 By whom built *Wigram & Green* Owners *R Green*
 Port belonging to *London* Destined Voyage
 If Surveyed Afloat or in Dry Dock *in Mess^{rs} Green's Dock*

Last Survey, No. *11578* Port of *London* Classed *A. 1*
Cont^d 49 4th A. 1

The present Condition of the

Decks <i>Good Caulked Good</i>	Treenails	Windlass and Capstan
Waterways <i>Doubled</i>	Breasthooks and Stenson	Pumps
Comings <i>10 pairs wood bolting fitted</i>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings <i>Good</i>	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales <i>Good all caulked</i>	Copper <i>ym</i> When put on <i>1849</i>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

at present upper deck waterways doubled and 10 pairs of single wood bolting thus fitted to the upper deck beams - yellow metal sheathing repaired is in efficient condition and is fit to remain as classed
 Committee Minute *18*
 Character assigned *A. 1*
 Certificate (if required)