

REPORT of SURVEY for REPAIRS.

16637

No. 18 Survey held at London Date July 10 18 57
 on the "Zephyr" Master James Peter Campbell
 Tonnage 272 Built at Sunderland When built 1844
 By whom built _____ Owners Chas. Leatham
 Port belonging to London Destined Voyage to America
 If Surveyed Afloat or in Dry Dock West India Dock

Last Survey, No. 10776 Port Spool Classed 9 A1

REPAIRS

new lower masts

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Efficient</u>
Waterways <u>do</u>	Breasthooks and Stenson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>Sound</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Good</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 B/W 15</u> <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>When put on 1850</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

She is in good & efficient condition and
and ready to receive cargo as directed

The Amount of Fee.....£ / : : is received by me, James Peter Campbell

Special..... : :

Certificate (if required) : :

Committee's Minute 15th March 1857

Character assigned 9 A1

Scrutton



© 2019

Lloyd's Register
Foundation

LON 630-0019