

REPORT of SURVEY for REPAIRS.

No. 838 on the *Bk "Asia"* Survey held at *London* Date *Feb 25 20* 1857
 Master *Woodward*
 Tonnage *455* Built at *Whitby* When built *1813*
 By whom built _____ Owners *Chapman*
 Port belonging to *London* Destined Voyage *Dublin*
 If Surveyed Afloat or in Dry Dock *Bull head Dry Dock*

Last Survey, No. *8757* Port *London* Classed *F 1*
42

REPAIRS

*Seeing this Ship in Dry Dock, renewing her Wood Sheathing
 I wrote the following request to the Owner, and received
 the reply which is here affixed.*

*Sir/ Perceiving your Bk "Asia" in Bull head Dry Dock, under
 "Repair and that she stands in the Register Book part -
 "Sheathed 1837 and has not been examined since 1842
 "I beg to be informed whether or not it is your wish
 "that she should be re-surveyed, and the new Sheathing
 "Reported to the Committee of this Society."*
E. H. Chapman Esq *Sam L L*

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

She has not been examined by me

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minutes

Character assigned

14th March 1857
to be struck out of the
Register Book



© 2019

Lloyd's Register
 Foundation

LON 630-0028