

REPORT of SURVEY for REPAIRS.

16648

No. 455 on the Bk Clara Survey held at London Date 4 Feb till 15 Mar 1851
 Master E. Potter
 Tonnage 368 Built at Yarmouth When built 1827
 By whom built S. Fletcher Owners S. Fletcher
 Port belonging to London Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock in Messrs Fletcher's Dock

st Survey, No. 15447 Port London Classed Regd. 1844. 7 yrs A 1

PAIRS

at Present this Vessel has been stripped of wood and yellow metal sheathing hung in shores and caulked from the Keel to the water ways, 3 iron hanging knees of hole beams on the larboard & 2 on the Starboard Side untold the repaired and refitted part new false keel fitted - bottom sheathed with wood and felt and bottom & sheathed with yellow metal - Hull, Mast & Rigging generally overhauled & refitted -

ent Condition of the

erways	Treenails	Windlass and Capstan
ings	Breasthooks and Stemson	Pumps
er Deck Beams & Fastenings	Transoms, Pointers, and Crutches	Boats
er Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
ksheers	Keelsons	Sails
rstrakes	Clamps and Shelves	Anchors No. of
ides	Ceiling	Cables
es	Rudder	Hawsers and Warps
rk (Bottom) and Counter	Copper <u>Ym</u> When put on <u>Feb 1851</u>	Standing & Running Rigging

ral Observations and Opinion,

This Vessel is in efficient Condition and may remain as Classed

Amount of Fee.....£ 2 : - : - is received by me,

Special..... 3 : 3 : -

Certificate (if required) : :

Committee's Minute 18th March 1851

Character assigned Fit to serve

Special Damage £ 3. 3



© 2019

Lloyd's Register Foundation

LON 630-0030