

REPORT of SURVEY for REPAIRS.

10087

No.

110

on the

Survey held at

London

Date 28. 20 June 1850

Master

E Thomas

Tonnage

141

Built at

Dundee

When built

1833

By whom built

Owners

E Thomas

Port belonging to

Cardigan

Destined Voyage

Archangel

If Surveyed Afloat or in Dry Dock

on Cripps Ways

Last Survey, No.

9015

Port

Spool

Classed

8 A1 1 expanded

REPAIRS

at Present all the Ribson Renewed of sheer bark
Culm and Clamps Fixed Rudder fastenings
overhauled Several treenails Renewed Caulking
of bottom overhauled -

Present Condition of the

Decks

Good

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrikes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stenson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper

New

Fixed

Overhauled

None When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Sufficient

for

Clap

Good

Good

and

Sufficient

General Observations and Opinion,

This Vessel is now fit for the safe conveyance
of dry perishable Cargoes and may
remain as Clap

The Amount of Fee.....£

: 10: -

is received by me,

Special.....

Certificate (if required) ..

: 5: -

Committee's Minute

Character assigned

8th April 1851

Fit for service

© 2019

Lloyd's Register
Foundation

LON 630-0070