

# REPORT of SURVEY for REPAIRS.

No. 121 on the *"M. Pearl"* Survey held at *London* Date *April 26* 18 *57*  
 Master *W. Harrison*  
 Tonnage *181* Built at *Scarb'ro* When built *1833*  
 By whom built *Lindall* Owners *Lindall*  
 Port belonging to *Scarb'ro* Destined Voyage *Tuckland, Ceylon*  
 If Surveyed Afloat or in Dry Dock *Dry Dock & Afloat*

Last Survey, No. *14874* Port *London* Classed *F11* S.S. *48*

## REPAIRS

At the present time New-grips fitted Several new Stairways new Side Counter timber, Small quantity of Cieling New Main deck, Cornings and fore hatch scuttle, New bulwarks, Keel beam and Hardsm ends and topsides caulked and generally overhauled,

## Present Condition of the

Decks <i>New Main</i>	Treenails <i>Good</i>	Windlass and Capstan <i>efficient</i>
Waterways <i>good</i>	Breasthooks and Stemson <i>do</i>	Pumps <i>do</i>
Comings <i>do</i>	Transoms, Pointers, and Crutches <i>do</i>	Boats <i>do</i>
Upper Deck Beams & Fastenings <i>Sound</i>	Timbers of the Frame <i>sound</i> <i>do</i>	Masts, Yards, &c <i>New Main Mast</i> <i>do</i>
Lower Deck Beams & Fastenings <i>do</i>	Keelsons <i>do</i>	Sails <i>do</i>
Plank sheers <i>good</i>	Clamps and Shelves <i>do</i>	Anchors No. of <i>21-1</i> <i>do</i>
Sheerstrakes <i>do</i>	Ceiling <i>do</i>	Cables <i>do</i>
Topsides <i>do</i>	Rudder <i>do</i>	Hawsers and Warps <i>do</i>
Wales <i>do</i>	Copper When put on <i>1848</i>	Standing & Running Rigging <i>do</i>
Plank (Bottom) and Counter <i>do</i>		

## General Observations and Opinion,

*She is now in a good and efficient condition and eligible to remain as classed for for the conveyance of dry and perishable cargo to & from all ports of the world.*


The Amount of Fee.....£ *1* : - : - is received by me,

Special.....

Certificate (if required) : *5* : -

Committee's Minute

Character assigned



© 2019

Lloyd's Register Foundation

LON 630-0085