

# REPORT of SURVEY for REPAIRS.

*Change of Owners*

No. *111* Survey held at *London* Date *10 June* 1857  
 on the *Br Thomas Hughes* Master *Ferguson*  
 Tonnage *310* Built at *Dundee* When built *1836*  
 By whom built \_\_\_\_\_ Owners *Mudcart*  
 Port belonging to *London* Destined Voyage *P<sup>r</sup> Phillip*  
 If Surveyed Afloat or in Dry Dock *in Duke Shore Dock*

Last Survey, No. *15991* Port *London* *Classed* *\*A 1*  
*C 3* *SS 47*

## REPAIRS

*at Present bottom stripped, Caul Red  
 and Sheathed with Yellow Metal on felt  
 Ceiling in hold doubled over and butts fastened  
 Under overhauled, Wals Caul Red*

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales <i>Caul Red</i>	Copper <i>Ym</i> When put on <i>June</i>	Standing & Running Rigging

## General Observations and Opinion,

*This Vessel appears in efficient Condition  
 and in my opinion fit for the safe  
 conveyance of dry perishable Cargoes*

The Amount of Fee.....£ 2 : : is received by me,

Special..... : : :

Certificate (if required) : 10 : -

Committee's Minute *20th June 1857*

Character assigned *H 1 1*

*to remain as before*

*to remain as before*

*Lloyd's Register  
 Foundation*