

REPORT of SURVEY for REPAIRS.

16950

No. 502 Survey held at London Date July 12th 1857
 on the Bk William & Mary Master R Peter
 Tonnage 450 Built at Sunderland When built 1849
 By whom built _____ Owners Mitcheson
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Young & Sons Dock

Last Survey, No. 15288 Port London 1849 Classed 10 A1

REPAIRS At the present time four pairs of iron riders two from aft & two from forward placed diagonally from the upper deck clamp down to the floor heads.
Bottom stripped & caulked & sheathed with yellow metal

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

Good good good Do Do Do well found No. of 3 Bower Stm & 2 kedge well found Do good

General Observations and Opinion, In a very efficient state to continue as classed

R. J. Mitcheson,

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 5th Aug 1857

Character assigned 10 A1



© 2019

Lloyd's Register
Foundation

LON 630-0337