

REPORT of SURVEY for REPAIRS.

16993

No. 483 Survey held at London Date 21st Aug 1857
 on the BK "Sydney" Master Clark
 Tonnage 313 Built at Shields When built 1840
 By whom built _____ Owners Carter
 Port belonging to London Destined Voyage America
 If Surveyed Afloat or in Dry Dock in Mr. Carter's Dock

Last Survey, No. 14729 Port London Classed NA 1
 Coats 1850-3 yrs

REPAIRS

at present docked to inspect the state of the
 yellow metal sheathing which is smooth
 and has been repaired the wales have been
 caulked - the bilge pumps repaired -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales <u>Caulked</u>	Copper <u>Ym</u> When put on <u>1858</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

This vessel is in efficient Condition
 and fit to remain as classed

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 22nd Aug 1857

Character assigned CR 3 A



© 2019

Lloyd's Register
 Foundation