

REPORT of SURVEY for REPAIRS.

16999

Rec 25/8/57

No. 123 Survey held at London Date 5th 8th Aug^r 1857
 on the Ship "Bengal" Master J Edington
 Tonnage 470 Built at Dumbarton When built 1845
 By whom built _____ Owners Campbell
 Port belonging to Glasgow Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock in Sunderland Dock

Last Survey, No. 9000 Port Lpool Classed 10 A 1

REPAIRS

at present bottom stripped hung Caulked
 and treenailed with yellow putty on
 dry Taper wales topsides sheerstrakes
 and water ways caulked - all the out
 tin bolts of the lower deck binding renewed
 of iron -

Present Condition of the

Decks	Treenails	Windlass and Capstan	<u>Good</u>
Waterways	Breasthooks and Stemson	Pumps	
Comings	Transoms, Pointers, and Crutches	Boats	<u>Good (Three)</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.	<u>Sufficient</u>
Lower Deck Beams & Fastenings	Keelsons	Sails	<u>Sufficient</u>
Planksheers	Clamps and Shelves	Anchors No. of	<u>3 1 2</u>
Sheerstrakes	Ceiling	Cables	<u>Sufficient</u>
Topsides	Rudder	Hawsers and Warps	<u>Do</u>
Wales	Copper	Standing & Running Rigging	<u>Do</u>
Plank (Bottom) and Counter	When put on		

General Observations and Opinion,

This Vessel is in efficient Condition
 and fit to remain as Classed

The Amount of Fee.....£..... is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 26th Aug^r 1857

Character assigned 10 A 1



© 2019

Lloyd's Register
Foundation

LON 630-0385