

REPORT of SURVEY for REPAIRS.

Change of Name 17022

No. 294 Survey held at London Date Aug 17 Sep's 18 57
on the M Senator Master A King
Tonnage 337 Built at Southampton When built 1843
By whom built 395 Owners Wm Harrison
Port belonging to London Destined Voyage Sidney
If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 15145 Port London Classed 12 A 1

REPAIRS

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>Wholesome</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>9 AIS/K</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>New Hemp Steam and</u>
Wales <u>do</u>	Copper <u>Wm</u> When put on <u>1849</u>	<u>and New Hawsers</u>
Plank (Bottom) and Counter <u>do</u>		Standing & Running Rigging <u>do</u>

General Observations and Opinion,

The ship is in good sufficient condition
and eligible to remain as classed

The Amount of Fee.....£ 2 : : is received by me, A King

Special..... : :

Certificate (if required) : :

Committee's Minute 12th Sept 1857

Character assigned 12 A 1



© 2019

Lloyd's Register
Foundation

LON 630-0408