

# ANNUAL SURVEYS.

17031

No. 205 Survey held at London Date Sept 8<sup>th</sup> 11 1857  
 on the Bk Champion Master Huntly  
 Tonnage 206 Built at Sunderland When built 1835  
 By whom built \_\_\_\_\_ Owners P. Tindall  
 Port belonging to London Destined Voyage Demerara  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 10207 Port of Singapore

1849 SS Classed AE 1st class  
 C 3 50

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>Do</u>	Breasthooks and Stemson <u>Do</u>	Pumps <u>Do</u>
Comings <u>Do</u>	Transoms, Pointers, and Crutches <u>Do</u>	Boats <u>Do</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good when seen</u>	Masts, Yards, &c. <u>Do</u>
Lower Deck Beams & Fastenings <u>Do</u>	Keelsons <u>Good</u>	Sails <u>well found</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>Do</u>	Anchors No. of <u>3 Bower 1 Stn 1 Hedge</u>
Sheerstrakes <u>Do</u>	Ceiling <u>Do</u>	Cables <u>well found</u>
Topsides <u>Do</u>	Rudder <u>Do</u>	Hawsers and Warps <u>Do</u>
Wales <u>Do</u>	Copper <u>When put on 1849</u>	Standing & Running Rigging <u>Good</u>
Plank (Bottom) and Counter <u>Good</u>		

General Observations and Opinion, At Jamaica in May 1849 shipped, caulked & sheathed with  
Copper overfelt and is in a very good condition for the safe  
conveyance of dry & perishable cargoes to & from all parts  
of the world and may continue as classed

Committee Minute 12<sup>th</sup> Sept 1857

Character assigned AE 1st class

Certificate (if required)

No. 169 Survey held at London Date Sept 10<sup>th</sup> 9 1857  
 on the Bk Hynes Master Burgess  
 Tonnage 299 Built at Bristol When built 1842  
 By whom built \_\_\_\_\_ Owners Thomson & Co  
 Port belonging to London Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 18757 Port of London

Classed 12A1  
 50

The present Condition of the

Decks <u>Good</u>	Treenails _____	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson <u>Good</u>	Pumps <u>Do</u>
Comings _____	Transoms, Pointers, and Crutches <u>Do</u>	Boats <u>Do</u>
Upper Deck Beams & Fastenings _____	Timbers of the Frame <u>Good when seen</u>	Masts, Yards, &c. <u>Do</u>
Lower Deck Beams & Fastenings _____	Keelsons <u>Good</u>	Sails <u>well found</u>
Planksheers _____	Clamps and Shelves <u>Do</u>	Anchors No. of <u>3 Bower 1 Stn &amp; Hedge</u>
Sheerstrakes _____	Ceiling <u>Do</u>	Cables <u>well found</u>
Topsides _____	Rudder <u>Do</u>	Hawsers and Warps <u>Do</u>
Wales _____	Copper <u>When put on 1847</u>	Standing & Running Rigging <u>Good</u>
Plank (Bottom) and Counter _____		

General Observations and Opinion, Break of the quarter deck has been lengthened 8 feet & done  
in a very efficient manner, & is in good condition to retain  
her present class

Committee Minute 12<sup>th</sup> Sept 1857

Character assigned 12A1

Certificate (if required)