

REPORT of SURVEY for REPAIRS.

17102

Recd by Mr

Supp⁴ No. Survey held at London Date Oct 29 1857
 on the Bk Columbia Master W Ellison
 Tonnage 416 Built at Sunderland When built 1850
 By whom built Owners Ridley & Co
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Fletcher's Dock

Last Survey, No. 4286 Port Sunderland Classed 10 A 1
 30

REPAIRS The yellow metal being wrinkled has been stripped, six pair of
 Iron riders fitted from the hold beam stamp down to the floors
 two bolts in a floor, two pair of Iron hanging ^{knives} to the hold beams
 in midships, bottom caulked & sheathed with yellow metal
 on paper

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>1857</u>	

General Observations and Opinion, Is in good condition to continue as classed

R. W. M. D. S. M.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : *14/11/57*

Certificate (if required) : :

Committee's Minute 18th Novr 1857

Character assigned 10 A 1



© 2019

Lloyd's Register
 Foundation
 LON 631-0116