

REPORT of SURVEY for REPAIRS.

17273

No. 680 Survey held at London Date Dec 23 to Jan 28 52
on the Bk Surge Master W. E. Maurice
Tonnage 411 Built at Sunderland When built 1843
By whom built _____ Owners Phillipps & Co
Port belonging to London Destined Voyage West India
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. 15025 Port London Classed 10 A1

REPAIRS

yellow metal stripped off, wood sheathing stripped off from the keel to the first foothook beam & that part of the bottom caulked & resheathed with inch boards on felt, and sheathed with yellow metal

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>4 1/4</u> When put on <u>1852</u>	Standing & Running Rigging

General Observations and Opinion, *I am a very efficient state to retain her present class*

The Amount of Fee.....£ 2 : : is received by me,

Special..... : : }

Certificate (if required) : 10 : -

Committee's Minute 16th Jan 1852

Character assigned 10 A1



© 2019

Lloyd's Register
Foundation

LON 631-0231