

REPORT of SURVEY for REPAIRS.

No. 439 Survey held at London Date Feb 7th 20 1852
 on the Bk Mary Ann Master Darke
 Tonnage 470 Built at Batavia When built 1840
 By whom built _____ Owners Darke
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Fletcher's Dock

Last Survey, No. 10790 Port London S.S. 47 Classed At Asterisk

REPAIRS Two lower breasthooks being defective have been taken out & replaced with two Iron ones, two filling cant timbers on each side, eight planks on each side in the ceiling in the way of the new hooks shifted 14 1/2 feet, ceiling repaired, new futting forward in the way of the way of the copper bolts in the breasthooks, 30 sheets of Copper replaced in the bins & caulked from the Copper over all

Why is the copper fee paid?

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of <u>3 Bower Stm & Sledge</u>
Sheerstrikes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>1851</u>	

General Observations and Opinion,

From her good condition am of opinion she is fit for the safe conveyance of dry & perishable cargoes to & from all parts of the world & may continue as classed

The Amount of Fee.....£ : : is received by me,

Special..... 2 : 2 : 11 } As

Certificate (if required) : 10 : -

Committee's Minute 5 hour 1852

Character assigned At 1 of Super



© 2019

Lloyd's Register Foundation

LON631-0322