

17370

# REPORT of SURVEY for REPAIRS.

No. ✓ Survey held at London Date 25 Feb 5 March 1852  
on the Ship "Ontario" Master J Watson  
Tonnage 460 Built at Dumbarton When built 1845  
By whom built \_\_\_\_\_ Owners Henderson  
Port belonging to Glasgow Destined Voyage \_\_\_\_\_  
If Surveyed Afloat or in Dry Dock In Globe Dock

Rec'd & Manned

Last Survey, No. 346 Port Glasgow Classed 10 A 1  
50

REPAIRS  
This Vessel Hullson was found decayed between the fore & main hatchways - and much of the hold Ceiling was also found in a defective state. and written notice was given to the Master to repair these parts - but the Owners has decided to take her down to the Clyde there to do the necessary repairs under the inspection of the local Surveyor (Mr Robertson) She has taken in chalk as ballast & is about to proceed to the Clyde

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion, Under the above stated Circumstances  
I am of opinion her Character should be  
Suspended until repaired

The Amount of Fee.....£ : : is received by me,

Special..... : :

J. H. Ritchie

Certificate (if required) : :

Committee's Minute 9th March 1852

Character assigned See Clyde No 598  
Glasgow

Wm. L. Lloyd  
Lloyd's Register  
Foundation

LON631-0328