

REPORT of SURVEY for REPAIRS.

Change of Owners

No. *4/8*
on the *S Ann*

Survey held at *London*

Date *Feb 27* 18 *52*

Master *J R Brown*

Tonnage *665*

Built at *Batavia*

When built *Prize*

By whom built

Owners *Carter & Sons*

Port belonging to *London*

Destined Voyage *Hong Kong*

If Surveyed Afloat or in Dry Dock *East India Dock & Dry Dock*

Last Survey, No. *15917*

Port *London*

Classed *FE 1st class*

REPAIRS

150 feet of new deck, 60 feet of new waterway ceiling repaired, new head knee, rails & bulking, caulked from the Copper over all & the buttock filled up & carried aft to improve her steering

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on *1851*

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of *3 Bows Skin & 2 Hedges*

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Am of opinion this vessel is in good condition for the safe conveyance of dry & perishable cargoes to & from all parts of the world and may retain her present class

The Amount of Fee.....£ *3* : — : is received by me,

Special.....

Certificate (if required) : *10* : —

Committee's Minute

Character assigned

© 2019

Lloyd's Register Foundation

LON631-0343