

REPORT of SURVEY for REPAIRS.

Change of Owners

No. 17559 Survey held at London Date 27 Feb 1852
 on the Ship "Saladin" Master J. H. Day
 Tonnage 172 Built at Sunderland When built 1851
 By whom built J. Crown Owners Henderson
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock in Sunderland Dock & Afloat

Last Survey, No. 4597 Port Sunderland Classed 13 A A

REPAIRS

at present four "eye bolts" fitted to Stern thro
 poop beams - Stern timbers bolted thro the wing
 transom with yellow metal - an iron breast
 hook fitted over the bowsprit. Sister Keelson
 additionally bolted - The bottom Caulked
 and Sheathed with yellow metal so felt
 Standing Rigging refitted

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>yes</u> When put on <u>March 1852</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

*This Vessel is in efficient Condition
 and fit to remain as classed*

The Amount of Fee.....£ 3 : : is received by me,


Special..... 5 : 5 : -

Certificate (if required) : :

Committee's Minute 11 June 1852

Character assigned 13 A A 1

Special £ 5. 5. -



© 2019

Lloyd's Register
 Foundation

LON 632 - 0009