

REPORT of SURVEY for REPAIRS.

17662

No. 146 Survey held at LONDON Date 28 May 1852
Dandy on the Smack "Edward James" Master Richmond
 Tonnage 58 Built at Ipswich When built 1836
 By whom built _____ Owners Captain J. G.
 Port belonging to Maldon Destined Voyage _____
 If Surveyed Afloat or in Dry Dock on Cress ways

Last Survey, No. 472 Port Ipswich Classed 10 expensed
Rest 1846. 7 yrs. 2

REPAIRS

at present from damage, new bowsprit and
 new false stem fitted - bows Caulked
 yellow metal sheathing repaired

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps <u>two</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>new bowsprit</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings	Keelsons	Sails <u>Sufficient</u>
Planksheers	Clamps and Shells	Anchors No. of _____
Sheerstrakes	Ceiling	Cables _____
Topsides	Rudder	Hawsers and Warps _____
Wales	Copper <u>Ym</u> When put on <u>when?</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter		

General Observations and Opinion,

This vessel appears in good and
 efficient condition & fit to remain as
 classed

The Amount of Fee.....£ — : 10 : — is received by me,
 21/7/52

Special..... : : :

Certificate (if required) : : :

Committee's Minute 8th Aug 1852

Character assigned Rest 7th 1
87



© 2019

Lloyd's Register
 Foundation

LON 632 - 0116