

REPORT of SURVEY for REPAIRS.

17194

No. 396 Survey held at London Date June 25 1852
 on the Bk John Hullett Master James Crouch
 Tonnage 284 Built at Sundaland When built 1841
 By whom built _____ Owners Blyths & Co
 Port belonging to London Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock West India Dock

Last Survey, No. 16995 Port London Can 1850 Classed 3 A1

REPAIRS New main deck of Dantzic red pine, & caulked from the
Copper overall

*Wrote to Messrs Blyths for a statement of the repairs done at the Mauritius
 the early part of July, but have not had an answer*

WM Aug^r 16th 1852

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>1849</u>	

General Observations and Opinion, In good condition & may continue as classed

W. Middleton

The Amount of Fee.....£ / : : is received by me, *W. Middleton*

Special..... : :

Certificate (if required) : :

Committee's Minute 17 Aug^r 1852

Character assigned CWP 3 A1



© 2019

Lloyd's Register
Foundation

LON 632-0149