

17740

REPORT of SURVEY for REPAIRS.

No. *Supp<sup>24</sup>* Survey held at *London* Date *14<sup>th</sup> Sept* 18*52*  
on the Ship *"Merchantman"* Master *J Grey*  
Tonnage *926* Built at *Sunderland* When built *1852*  
By whom built *J. Laing* Owners *Somes Brothers*  
Port belonging to *London* Destined Voyage *Bombay*  
If Surveyed Afloat or in Dry Dock *in Mr Somes's Dock*

*Rec'd 15 Sept*

Last Survey, No. *4813* Port *Sunderland* Classed *13 A 1*

REPAIRS *at present Caulked to the top of the wales (from the keel) and the bottom sheathed with yellow metal on paper*

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <i>Leak</i>
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <i>Ym</i> When put on <i>Sept 1852</i>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

*This fine ship is in the highest state of efficiency & fit to remain as closed*

The Amount of Fee.....£..... is received by me,

*A. H. Ritchie*

Special..... : :

Certificate (if required) : :

Committee's Minute *17<sup>th</sup> Sept 1852*

Character assigned *13 A 1*  
*revd Ym. J. D.*

