

REPORT of SURVEY for REPAIRS.

17807

No. 23 Survey held at London Date 25th Sep 1852
 on the BK "Katharine Sharer" Master T Taylor
 Tonnage 440 Built at Sunderland When built 1850
 By whom built _____ Owners Sharer & Co
 Port belonging to Sunderland Destined Voyage China
 If Surveyed Afloat or in Dry Dock in Dry Dock

Last Survey, No. 4382 Port Sunderland Classed 12 A 1

REPAIRS

at present from damage bottom stripped, hung
 Caulked to the wales and bottom resheathed with
 yellow metal - new figure head fitted

Present Condition of the

Decks	Trreenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>Sept</u>	

1852

General Observations and Opinion,

This Vessel is in efficient Condition.
 and fit to remain as Classed

The Amount of Fee.....£ : : is received by me,

Special..... : : :

Certificate (if required) : : :

Committee's Minute 19 Ope 1852

Character assigned 12 A 1

Special Damage £3.5

© 2019

Lloyd's Register
 Foundation

LON 632-0265