

# REPORT of SURVEY for REPAIRS.

17957

No. 6 Survey held at London Date Dec 1/Jan 5 1853  
 on the MS Labuan Master W Scott  
 Tonnage 456 Built at Sunderland When built 1847  
 By whom built 547 Owners Brass  
 Port belonging to London Destined Voyage -  
 If Surveyed Afloat or in Dry Dock Wichers Dock & W & D

Last Survey, No. 15/11 Port London Classed 12 A1  
 57

## REPAIRS

At the present time Shipped 4 new fore boards of bottom on each side foreward from horns, Coaked from Shetted up and Sheathed with Gum India upon paper

### Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stenson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>Wholesome</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>9/1</u> <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>Painted</u> When put on <u>1852</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		<u>See above</u>

### General Observations and Opinion,

She is in good and efficient Condition and likely to remain as Clipped.

The Amount of Fee.....£ : : is received by me,

Special..... 2 : 2 : -

Certificate (if required) : 10 : -

Committee's Minute 11th Jan'y. 1853

Character assigned 12 A1



© 2019

Lloyd's Register Foundation

LON 632-0409