

18011

REPORT of SURVEY for REPAIRS.

Change of Owners

No. 423

on the

Survey held at

London

Date

10th Dec^r

1852

Tonnage

417

Built at

Sunderland

When built

1838

By whom built

Owners

~~Temporarily~~ Smith & Co

Per Ship Smith & Co

Port belonging to

London

Destined Voyage

If Surveyed Afloat or in Dry Dock

in Messrs Fletcher & Co Dock

Last Survey, No.

11935

Port

London

Classed

A A

REPAIRS

at present docked to inspect the state of the yellow metal sheathing which has been repaired planks sheers & waterway beams caulked

Present Condition of the

Decks

Waterways *caulked*

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers *caulked*

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on 1851

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of 3 1 2

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

This vessel is in excellent Condition and fit to remain as classed

J. H. Ritchie

The Amount of Fee.....£ 2 : - : - is received by me,

Special.....

Certificate (if required)

Committee's Minute

4th July 1853

Character assigned

Class 4 A



© 2019

Lloyd's Register Foundation

LON 632-0471