

# ANNUAL SURVEYS.

18071

No. 13 Survey held at London Date Feb 25 to March 1 1853  
 on the B<sup>le</sup> Leonard Dobbin Master Wilson  
 Tonnage 111 Built at Quebec When built 1837  
 By whom built \_\_\_\_\_ Owners L. Wilkinson  
 Port belonging to Whitby Destined Voyage Quebec  
 If Surveyed Afloat or in Dry Dock Lavender Dry Dock

C. C. M. M.

Last Survey, No. 13 Port of London Classed A 1  
 S. D. 50. 599 5<sup>th</sup> 1853

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches } <u>Good</u>	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. } <u>In good order</u>
Lower Deck Beams & Fastenings } <u>Do</u>	Keelsons } <u>do</u>	Sails } <u>and sufficient</u>
Planksheers	Clamps and Shelves } <u>do</u>	Anchors No. of
Sheerstrakes } <u>do</u>	Ceiling } <u>do</u>	Cables
Topsides } <u>do</u>	Rudder } <u>do</u>	Hawsers and Warps
Wales } <u>do</u>	Copper } <u>When put on</u>	Standing & Running Rigging
Plank (Bottom) and Counter } <u>do</u>		

General Observations and Opinion.  
None done. Yellow metal sheathing stripped off the Bottom and not renewed; all Treenails tiled by the Caulkers, and the Outside Caulked entirely. She appears to be in good

Committee Minute 4<sup>th</sup> March 1853 condition, eligible to remain as

Character assigned A 1 Classed A 1 J. D. Martin  
Survey 5.72 Certificate (if required)

No. 13 Survey held at London Date Feb 25 to Mar 1 1853  
 on the B<sup>le</sup> Mandarin Master Symons  
 Tonnage 315 Built at Scilly When built 1849  
 By whom built \_\_\_\_\_ Owners Tregathan  
 Port belonging to Scilly Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock In Mountain Dry Dock

Last Survey, No. 13 Port of Scilly Classed 12 A 1  
 S. D. \_\_\_\_\_ 5<sup>th</sup> 1853

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches } <u>Good</u>	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. } <u>In good order</u>
Lower Deck Beams & Fastenings } <u>Do</u>	Keelsons } <u>do</u>	Sails } <u>and sufficient</u>
Planksheers	Clamps and Shelves } <u>do</u>	Anchors No. of
Sheerstrakes } <u>do</u>	Ceiling } <u>do</u>	Cables
Topsides } <u>do</u>	Rudder } <u>do</u>	Hawsers and Warps
Wales } <u>do</u>	Copper } <u>When put on</u>	Standing & Running Rigging
Plank (Bottom) and Counter } <u>do</u>		

General Observations and Opinion.  
None done. Yellow metal sheathing stripped off Bottom Caulked and re-sheathed with Metal on Paper. She appears to be in good condition eligible to remain Classed A 1

Committee Minute 4<sup>th</sup> March 1853

Character assigned 12 A 1 Classed A 1 J. D. Martin  
Survey 5.72 Certificate (if required)

LON 633-0010