

18197

REPORT of SURVEY for REPAIRS.

Change of Names

No. 3 Survey held at London Date 4th May 1853
 on the Wm Mc Donnell Master T. B. Cox
 Tonnage 513 Built at New Brunswick When built 1845
 By whom built _____ Owners Langley & Co
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Runes dry Dock

Last Survey, No. 17251 Port London Classed 6 SS. 51-47

REPAIRS *This ship has had the yellow metal stripped off and caulked from keel to lower part of wales and sheathed with zinc over patent felt.*

Present Condition of the		
Decks <u>Good</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>good where seen</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>Sufficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>two Sets</u>
Plankwalkers <u>do</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 1/2</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>Sufficient</u>
Topsides <u>do</u>	Rudder <u>Good</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>Zinc</u> When put on <u>now</u>	Standing & Running Rigging <u>Good</u>
Plank (Bottom) and Counter		

General Observations and Opinion, *This ship appears to be in fair condition and eligible to remain as classed A.1.*


The Amount of Fee.....£ 3 : : is received by me, H. M. M. Sutyo

Special.....

Certificate (if required) : :

Committee's Minute 13 May 1853

Character assigned Class 2



© 2019 Lloyd's Register Foundation