

REPORT of SURVEY for REPAIRS.

18553

No. 218 Survey held at London Date 3rd June 1855
 on the Ship "Arkbar" Master _____
 Tonnage 718 Built at Sunderland When built 1851
 By whom built _____ Owners Lascombe
 Port belonging to London Destined Voyage St Philip
 If Surveyed Afloat or in Dry Dock in Young's Dock

Last Survey, No. 17029 Port London Classed B A 1

REPAIRS

at Present bottom Stopped Caulked and
 sheathed with yellow Metal in felt above
 and Paper below hoarding ends Caulked and
 tight 6 pairs of Iron hold Vices fitted Yellow
 Metal bottom - Standing Rigging refitted -

Present Condition of the

| | | |
|-------------------------------|--|----------------------------|
| Decks | Treenails | Windlass and Capstan |
| Waterways | Breasthooks and Stenson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Keelsons | Sails |
| Planksheers | Clamps and Shelves | Anchors No. of |
| Sheerstrakes | Ceiling | Cables |
| Topsides | Rudder | Hawsers and Warps |
| Wales | Copper <u>4 M</u> When put on <u>June</u> 18 <u>55</u> | Standing & Running Rigging |
| Plank (Bottom) and Counter | | |

General Observations and Opinion,

This Vessel is in efficient Condition
 and fit to remain as Classed

The Amount of Fee.....£ : : is received by me,

Special..... : : St. R. Ritchie

Certificate (if required) : : Charles Ormerod

Committee's Minute 18th July 1855

Character assigned 13

Lloyd's Register
 Foundation