

18433

REPORT of SURVEY for REPAIRS.

No. 14783 Survey held at London Date 11/8/53
on the SS Madras Master Hilbery
Tonnage 331 Built at Whithaven When built 1824
By whom built _____ Owners Hilbery
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock West India Dock Afloat

Last Survey, No. 14783 Port London Classed A.1
REPAIRS At the request of the owner a survey was held on this vessel when I found the Ceiling, Nelson, and Greenalls a great portion of them badly decayed sent written notice 11 July recommending the above repairs

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shells	Anchor No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	When put on
Plank (Bottom) and Counter		Standing & Running Rigging

General Observations and Opinion, This vessel now in the West India Dock and taking on Board Cargo has not had any repairs recommended done, and I am of opinion her Character should be suspended until repaired

The Amount of Fee, £ _____ is received by me,

Special, _____

Certificate (if required) _____

Committee's Minute 23rd Aug 1853

Character assigned George Chapman

Lloyd's Register
Foundation

L: 24/9/53

LOW 633-034