

184/61

REPORT of SURVEY for REPAIRS.

No. 44 Survey held at London Date 27 July 1853 *Rev 20/8/53*
 on the Ship "Earl of Hardwicke" Master W. Pope
 Tonnage 1000 Built at London When built 1838
 By whom built 903 Owners Richard Green
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Green dry Dock and East India St

Last Survey, No. 17716 Port London Classed 12 A/V 50/490

REPAIRS At the present time the After piece of Sides has been
Waterways doubled with dantzig Pine and the Wales
Patencained and Sixteen pair of Wood Lacing Pieces
added to upper deck Beams at the Owners request.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>White</u> When put on <u>1852</u>	Standing & Running Rigging <u>Good</u>
Plank (Bottom) and Counter		

Good when taken down
Good Efficient

General Observations and Opinion, This Ship appears to be in good condition
at present and fit to remain as classed.


The Amount of Fee.....£ 3 : - : is received by me, M. S. S. S.

Special..... : : :

Certificate (if required) : 10 : - : ✓

Committee's Minute 6 Sept 1853

Character assigned CP 11



© 2019 Lloyd's Register

Lloyd's Register Foundation