

REPORT of SURVEY for REPAIRS.

No. 17143 Survey held at London Date 19th Sept 1853
 on the Ship Adelaide Master Stephen
 Tonnage 440 Built at Calcutta When built 1833
 By whom built _____ Owners James Wright
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock East India Dock Afloat and James Dry Dock

Last Survey, No. 17143 Port London Classed 1841
 REPAIRS At the present time the Stenson and Stenson once being defective has now been removed and renewed with English Oak. The Heel of Foremast of Keel defective has been tongued and properly hooked

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>1851</u>	

General Observations and Opinion, This Ship is now in good Condition and fit for the Slave Conveyance of any and Perishable Cargoes to and from all parts of the World and fit to remain as above

The Amount of Fee.....£ : : is received by me,

Special..... 2 : 2 : 0

Certificate (if required) : :

Committee's Minute 9th Sept 1853

Character assigned 111 Mark Good repair

No Repair paid

LEN 633-0405