

REPORT of SURVEY for REPAIRS.

1849

No. 17409 Survey held at London Date July 26th 18 53
 on the Ship Castle Eden Master Young
 Tonnage 76 Built at Sunderland When built 1842
 By whom built _____ Owners Somerset
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Somerset Canal dry dock.

Last Survey, No. 17409 Port London Classified G A II
 REPAIRS Cont 251 3 52

At present, yellow metal patched.
 This ship on the night of the 25th July 1853 just as she was taking the blocks slipped off ~~the~~ on to the dock bottom. — At the request of "Mr Preston" I went all over her, and could not discover any symptoms of damage.

Present Condition of the

Decks <u>Good</u>	Treenails _____	Windlass and Capstan _____
Waterways <u>do</u>	Breasthooks and Stenson _____	Pumps _____
Comings <u>do</u>	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shells _____	Anchors No. of _____
Sheerstrakes <u>Good</u>	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper <u>Yellow</u> When put on <u>1852</u>	Standing & Running Riggins _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

This vessel is in efficient condition and may remain as classed.

The Amount of Fee.....£ : : is received by me, Charles Porter

Special..... 1 : 1 : - 11

Certificate (if required) : : _____

Committee's Minute 26th Sept 1853

Character assigned Part 3 A

Special L.S. 1.0.

© 2019

Lloyd's Register Foundation

LON 633-0436