

*18532

REPORT of SURVEY for REPAIRS.

No. ✓ Survey held at London Date 16th Sept 1853
 on the Barclada Master J.M. Wear
 Tonnage 311 Built at Yarmouth When built 1825
 By whom built _____ Owners Wear
 Port belonging to Starkie Destined Voyage unknown
 If Surveyed Afloat or in Dry Dock Afloat in Miss Innes Dock

Last Survey, No. 13789 Port London Classed Ship, omitted

REPAIRS

At the present time an application left by the owner for classing.

And on examination found the Sides and Waterways also Shells of upper Deck and part of the Beams Defective from Decay. also the Ceiling in the lower Hold is in a bad state.

On pointing out the above to the owner he has declined entering in to those repairs for the present.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

From the present condition of this ship I cannot recommend her for any Character until repaired.

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 :

Certificate (if required) : :

Committee's Minute 18

Character assigned See Bristol No. 1824

Jan 1-1854

LON 633-0421

© 2019

Lloyd's Register
Foundation