

REPORT of SURVEY for REPAIRS.

1855

No. ³² Survey held at London Date 4th Decr 20th 1853
 on the Ship Windsor Master T. B. Callinan
 Tonnage 1099 Built at Quebec When built 1830
 By whom built _____ Owners J. Smith & Co
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock in Mr. Wiggins & London Dock

Last Survey, No. 11328 Port Liverpool Classed 5 AA

REPAIRS at present bottom stripped Caulked and
 sheathed with yellow metal. Several
 bolts of iron ridges driven out for inspection
 and found good

Written notice given on the 15th July (which
 had not been complied with on the 20 Augr) to
 furnish the ship with 45 fathoms of 1 1/2" Chain
 and a bow, and stream anchor

Present Condition of the

Decks <u>Good</u>	Treenails _____	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stenson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings <u>fair</u>	Timbers of the Frame _____	Masts, Yards, &c. <u>Sufficient</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons _____	Sails _____
Planksheers } <u>Good</u>	Clamps and Shelves } <u>Good</u>	Anchors No. of } <u>See</u>
Sheerstrakes } <u>Good</u>	Ceiling _____	Cables } <u>Certificates</u>
Topsides _____	Rudder _____	Hawsers and Warps <u>useable</u>
Wales _____	Copper <u>fine</u> When put on <u>11th June 1853</u>	Standing & Running Rigging <u>Sufficient</u>
Plank (Bottom) and Counter _____		

General Observations and Opinion,

This vessel having been furnished with
 the necessary stores as appears from the Vouchers
 herewith and being in efficient condition is
 The Amount of Fee £ 3 : - is received by me, Chas. B. Callinan

Special..... £ 2 : -

Certificate (if required) : £ 10 : -

Committee's Minute 21 Decr 1853
 Character assigned 5 1 Good & Charles B. Callinan
 Special £ 2. 2 SB