

REPORT of SURVEY for REPAIRS.

18634

No. 283 Survey held at London Date Nov 24th 20 1853

on the Brig "Plumstead" Master

Tonnage 214 Built at Yarmouth When built 1837

By whom built Owners Messrs Hall Bros

Port belonging to London Destined Voyage Australia

If Surveyed Afloat or in Dry Dock In Messrs Young Son & Co Dry Dock

Last Survey, No. 16775 Port London Classed 12 A 1
 Cont 49. 4 51

REPAIRS

Now done. Yellow Metal Sheathing stripped off and renewed, and the Bottom Caulked.

Topsides, and Sheerstrakes scraped bright.
 The Sheer Strakes have an unhealthy appearance, no means afforded for their examination.

Sent Notice Card to Owners on the 24th inst. "Recommending as highly desirable that this Vessel be submitted to Survey before Reporting as fit for any character."
 Signed J. P. Martin

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Monday 11 Nov 20 The Ship was undocked yesterday, and the Owner has called at this Office to state that "the request cannot at present be complied with, she being under engagement to sail shortly."

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 29 Nov 18 53

Character assigned

J. P. Martin
M. M. Intype
Wrote to Owner
29 Nov