

18806

# REPORT of SURVEY for REPAIRS.

No. 231 Survey held at London Date 28<sup>th</sup> Feb / March 1854  
on the Brig "Liber" Master \_\_\_\_\_  
Tonnage 177 Built at Garnmouth When built 1830  
By whom built \_\_\_\_\_ Owners Robinson  
Port belonging to London Destined Voyage Australia  
If Surveyed Afloat or in Dry Dock Afloat in West India Dock

Last Survey, No. 3197 Port Glyde Classed 10 \* A. 1 59.47  
C 3 6

REPAIRS This vessel was lying in the West India Dock when on examination her The Bilge planks of ceiling was found much decayed also the outside planking where they could be examined appears also defective on the 28 Feb.  
A notice card was sent to the Owner recommending the defective planking inside and outside to be removed and the vessel submitted for further survey

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

## General Observations and Opinion,

The Yellow Metal on bottom appears to be worn out and several pieces off the Bottom, and as they are intending to send this vessel out to Melbourn I am of opinion she is unfit to retain her present Class


The Amount of Fee.....£ : : is received by me, M. M. Intype

Special..... : :

Certificate (if required) : :

Committee's Minute 13<sup>th</sup> March 1854

Character assigned Springer Carriers



LON 634-0224