

ANNUAL SURVEYS.

18807

No. ¹⁰ Survey held at London Date 24th 25th Feb^r 1854
 on the Ship "Ballarat" Master Jones
 Tonnage 657 Built at Aberdeen When built 1852
 By whom built _____ Owners Dent
 Port belonging to London Destined Voyage Port Philip
 If Surveyed Afloat or in Dry Dock Young's dry dock

Last Survey, No. 17689 Port of London Classed 12 A
 32

The present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson	"	Pumps	
Comings	"	Transoms, Pointers, and Crutches	"	Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame	"	Masts, Yards, &c.	<u>Good and</u>
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	<u>sufficient</u>
Planksheers	"	Clamps and Shelves	"	Anchors No. of	
Sheerstrakes	"	Ceiling	"	Cables	
Topsides	"	Rudder	"	Hawsers and Warps	
Wales	"	Copper <u>Y. Metal</u> When put on <u>1852</u>		Standing & Running Rigging	
Plank (Bottom) and Counter	"				

General Observations and Opinion, Now done - The Yellow Metal patched in places, where it had been rubbed by the cable. She is in a good and efficient state of repair and fit, in our opinion, to remain as classed.

Richard Aberkell
M. M. Intyre

Committee's Minute 3rd March 1854

Character assigned 12 A

Certificate (if required)

No. ³⁵ Survey held at London Date 1st March 1854
 on the Ship "Tartar" Master _____
 Tonnage 641 Built at Greenock When built 1851
 By whom built _____ Owners Adams & Co
 Port belonging to Greenock Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Young's dry dock

Last Survey, No. 2975 Port of Clyde Classed 13 A
 51

The present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson	"	Pumps	
Comings	"	Transoms, Pointers, and Crutches	"	Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame	"	Masts, Yards, &c.	<u>Good and</u>
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	<u>sufficient</u>
Planksheers	"	Clamps and Shelves	"	Anchors No. of	
Sheerstrakes	"	Ceiling	"	Cables	
Topsides	"	Rudder	"	Hawsers and Warps	
Wales	"	Copper <u>Y. Metal</u> When put on <u>Now</u>		Standing & Running Rigging	
Plank (Bottom) and Counter	"				

General Observations and Opinion, Now done - Yellow metal stripped off, the bottom caulked, and the Yellow metal renewed over dry paper. She is in a good and efficient condition, and is, in our opinion, eligible to remain as classed.

Richard Aberkell
M. M. Intyre

Committee's Minute 3rd March 1854

Character assigned 13 A

Certificate (if required)