

REPORT of SURVEY for REPAIRS.

18831

No. 380 Survey held at London Date 8th Feb^y & 8th Mar 1854
 on the Ship "Amazon" Master Cooke
 Tonnage 667 Built at Durdee When built 1850
 By whom built _____ Owners Somes Bro^r
 Port belonging to London Destined Voyage Bermuda
 If Surveyed Afloat or in Dry Dock Somes' dry docks & afloat in the river

Last Survey, No. 17093 Port London Classed 14 A1

REPAIRS Now done:- Yellow metal sheathing stripped off, the Bottom caulked from keel to Wales, and the Yellow metal renewed over tarred felt. Five of the Hold beams which were badly rent, partially decayed, and of inferior materials, have been removed and renewed.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>Good and</u>
Lower Deck Beams & Fastenings <u>Good where</u>	Keelsons <u>Good where</u>	Sails <u>sufficient</u>
Planksheers <u>seen</u>	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>& Metal</u> When put on, <u>now</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, This vessel appears to be in a good and efficient state of repair, and eligible, as far as we had an opportunity of judging, to remain classed A1

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 10 March 1854

Character assigned 14 A1