

REPORT of SURVEY for REPAIRS.

18896

No. 698 Survey held at London Date 21 March 1854
 on the Etheldred Master Butcher
 Tonnage 421 Built at London When built 1811
 By whom built _____ Owners Hopper
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Fletcher's Dry Dock

Last Survey, No. 17812 Port London Classed A1
 52

REPAIRS

At present nine Hold Beams renewed with American Oak one Iron Hook and one pair of Pointers hung in Shores and Caulked from Keel upwards and the Bottom Sheathed with Yellow Metal over the bare Plank

Present Condition of the

Decks <u>fair for class</u>	Treenails <u>good when seen</u>	Windlass and Capstan _____
Waterways <u>Good for class</u>	Breasthooks and Stemson <u>fair for class</u>	Pumps _____
Comings <u>Do</u>	Transoms, Pointers, and Crutches <u>Do</u>	Boats _____
Upper Deck Beams & Fastenings <u>Good when seen</u>	Timbers of the Frame <u>good when seen</u>	Masts, Yards, &c. <u>Good & safe</u>
Lower Deck Beams & Fastenings <u>Do</u>	Keelsons <u>Do</u>	Sails _____
Planksheers _____	Clamps and Shelves <u>Good for class</u>	Anchors No. of <u>3 B.W. 14</u>
Sheerstrakes <u>Good for class</u>	Ceiling <u>fair</u>	Cables _____
Topsides _____	Rudder <u>Good</u>	Hawsers and Warps <u>Good & safe</u>
Wales _____	Copper <u>Yellow Metal When put on new iron</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

The above repairs being done she is now in a fit condition for the conveyance of dry and perishable cargoes eligible to retain the A1 Character M M Intyre


The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 7th April 1854

Character assigned A1



Lloyd's Register Foundation

LON 634-0316