

19022

REPORT of SURVEY for REPAIRS.

No. 4 Survey held at London Date May 19th 1854
on the Brig "Sberia" Master _____
Tonnage 174 Built at Scarborough When built 1825
By whom built _____ Owners Williams X Fee
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Gun Dock Ways

Last Survey, No. 17622 Port London Classed A.1.
52

REPAIRS
On examination we found the buttocks and bows much wormed close above the Zinc sheathing: the ceiling and decks in a bad condition with one beam broken -
Sent a notice card to the effect that the above mentioned defects should be made good for the vessel to retain her class.
On enquiry this morning found they do not intend to enter into the required repairs.

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, We are of opinion that in her present condition, she is not fit for the conveyance of any and perishable Cargoes, nor fit for any class.

The Amount of Fee.....£ : : is received by me, P. Wainman
Special..... : : J. H. H. H.
Certificate (if required) : :

Committee's Minute 23rd May 1854

Character assigned Open Character - Not to be used
L.D.