

19039

Change of Owners

# REPORT of SURVEY for REPAIRS.

No. 469 Survey held at London Date 28th April 1854  
on the Ship "Subahdar" Master Uniferville  
Tonnage 634 Built at Dumbarton When built 1845  
By whom built \_\_\_\_\_ Owners Uniferville  
Port belonging to London Destined Voyage Calcutta  
If Surveyed Afloat or in Dry Dock Messrs Young Son & Co dry Dock  
Shew Bridge

Last Survey, No. 17630 Port London Classed 10 A 1

REPAIRS None at present. The yellow Metal sheathing  
stripped off the bottom and caulked from keel  
upwards including Decks. All the wasted Iron  
Boots in throats of Iron hanging knees to hold  
Beams driven out and renewed with yellow  
Metal Boots. One Strake of Deck plank next  
waterways on each side removed and replaced  
with new

## Present Condition of the

Decks <u>Good</u>	Treenails _____	Windlass and Capstan _____
Waterways <u>Do</u>	Breasthooks and Stemson <u>Good</u>	Pumps _____
Comings <u>Do</u>	Transoms, Pointers, and Crutches <u>Do</u>	Boats _____
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good</u>	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings <u>Do</u>	Keelsons <u>Do</u>	Sails <u>Good</u>
Planksheers <u>Do</u>	Clamps and Shelves <u>Do</u>	Anchors No. of <u>BB 1 1/2</u> <u>Haft</u>
Sheerstrakes <u>Do</u>	Ceiling <u>Do</u>	Cables _____
Topsides <u>Do</u>	Rudder <u>Do</u>	Hawsers and Warps _____
Wales <u>Do</u>	Copper <u>Y.M.</u> When put on <u>new</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter <u>Do</u>		

General Observations and Opinion, This ship appears to be in good condition  
and fit to remain as classed


The Amount of Fee.....£ 1 : : is received by me, M. M. Intype  
J. Alexander

Special..... : :

Certificate (if required) : :

Committee's Minute 30th May 1854

Character assigned 10 A 1 Uniferville



© 2019

Lloyd's Register

FOUNDED 1780