

REPORT of SURVEY for REPAIRS.

No. 26 Survey held at London Date 4th July 1854
on the Brig James Master J A Crundall
Tonnage 173 Built at Perth When built 1840
By whom built _____ Owners J Tobitt
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Saint Katherine Dock

Last Survey, No. 12207 Port Liverpool Classed - Class omitted

REPAIRS

In accordance with an order for survey on this vessel dated 1st Inst^l I called on board of her & found her to have a large quantity of shingle ballast on board extending fore & aft. The Ceiling along Jambships adjoining the ballast appeared in defective condition & the general appearance of the vessel in her outside plating from the metal sheathing upwards appeared to render a careful survey of her advisable. Recommended the ballast to be taken out & the hold cleaned the vessel scraped outside from the Gunwale to Metal sheathing after which put into dry Dock or laid upon the ways & intimation given when these were completed ready for survey.

Since the above date I have not heard any thing further of this vessel & I presume in consequence she has proceeded round to a coal port.

Special £1.1.0

Thomas Alexander

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 14th July 1854

Character assigned Good Survey

[Signature]



© 2019

Lloyd's Register
Foundation

LOV 635-0019