

# ANNUAL SURVEYS.

19307

No. <sup>30</sup> *1* Survey held at *London* Date *21<sup>st</sup> Sept* 185 *4*  
 on the Ship *"Marborough"* Master *Young*  
 Tonnage *1293* Built at *Newcastle* When built *1846*  
 By whom built \_\_\_\_\_ Owners *Smith & Co*  
 Port belonging to *London* Destined Voyage *Calcutta*  
 If Surveyed Afloat or in Dry Dock *Tome's dry dock*

*J. J. J.*  
*Dec 19 1854*

Last Survey, No. *18627* Port of *London* Classed *12 A 1*  
53


The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <i>Good and</i>
Lower Deck Beams & Fastenings <i>Good</i>	Keelsons <i>Good</i>	Sails <i>sufficient</i>
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <i>Y. Metal</i> When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, *This vessel is in a good and efficient state of repair and is, in my opinion, eligible to remain as she is.*

*Richard A. M. M.*

Committee's Minute *17<sup>th</sup> Oct* 185 *4*  
 Character assigned *12 A 1*



Lloyd's Register  
 Foundation

Certificate (if required)

L00635-0204