

ANNUAL SURVEYS.

19309
Dec 14 1854

No. 118 Survey held at London Date 6th October 1854
on the Barque "Admiral Grenfell" Master Machalland
Tonnage 324 Built at Bideford When built 1857
By whom built _____ Owners Miller & Co
Port belonging to Liverpool Destined Voyage _____
If Surveyed Afloat or in Dry Dock Young's dry dock

Last Survey, No. 10101 Port of Liverpool Classed 13 A 1
53

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame <u>Good where</u>	Masts, Yards, &c. <u>Good and</u>
Lower Deck Beams & Fastenings <u>Good</u>	Keelsons <u>seen</u>	Sails <u>sufficient</u>
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Yellow metal</u> When put on <u>now</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>on paper</u>	

General Observations and Opinion, Now done, yellow metal sheathing stripped off and renewed on paper - Caulked from keel to Copper line -
She is in a good and efficient state of repair, and eligible in my opinion to remain as classed.

Committee's Minute 17th November 1854 Richard A. Bethell

Character assigned 13 A 1 record
[Signature]

Certificate (if required)

No. _____ Survey held at London Date 1st Nov^r 1854
on the Barque "Vere" Master Doyd
Tonnage 300 Built at Sunderland When built 1833
By whom built _____ Owners James Thomson
Port belonging to London Destined Voyage Jamaica
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper _____ When put on _____	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Committee's Minute _____ 18

Character assigned _____



© 2019

Lloyd's Register
Foundation

Certificate (if required)