

No. 62 Survey held at LONDON Date 16 Decr 1854  
on the Ship "Saladin" Master John Myers  
Tonnage 772 Built at Sunderland When built 1851  
By whom built \_\_\_\_\_ Owners Henderson  
Port belonging to LONDON Destined Voyage Black Sea  
If Surveyed Afloat or in Dry Dock in East India Dock

Last Survey, No. 18258 Port of LONDON Classed 13A1

The present Condition of the

Decks <u>Good</u>	Treenails _____	Windlass and Capstan <u>Good</u>
Waterways <u>Caulking</u>	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats <u>four new</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>Good</u>	<u>new fore mast &amp; fore yard</u>
Lower Deck Beams & Fastenings <u>firm</u>	Keelsons _____	Masts, Yards, &c. <u>yellow &amp; red</u>
Planksheers _____	Clamps and Shelves _____	Sails <u>sufficient</u>
Sheerstrakes _____	Ceiling _____	Anchors No. of <u>3</u>
Topsides <u>Good</u>	Rudder <u>new tiller &amp; main</u>	Cables <u>sufficient</u>
Wales _____	<u>firm</u>	Hawsers and Warps <u>refitted new lanyards</u>
Plank (Bottom) and Counter _____	Copper <u>smooth &amp; good</u>	Standing & Running Rigging _____

General Observations and Opinion,

At present Hull, masts, & rigging over-  
hauled and the latter refitted & in efficient  
condition and fit to remain as before

Committee Minute 22nd December 1854

Character assigned 13A1