

19499

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date 4 Feb. 1853
on the B^d Anna Mary Master Stephen
Tonnage 302 Built at Sunderland When built 1847
By whom built _____ Owners Wainwright & Co
Port belonging to Bauff Destined Voyage Sydney
If Surveyed Afloat or in Dry Dock Bilbes Dock

Rev 19 Feb

Last Survey, No. _____ Port _____ Classed 10 A 1

REPAIRS

at present the iron bolts of the lower deck building below the line of the Copper renewed of yellow metal one new half beam fitted in the hold - water pipes and shearstrokes, Caulked - the bottom stripped hung Caulked and sheathed with yellow metal on full

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Ym</u> When put on <u>Feb</u>	Standing & Running Rigging
Plank (Bottom) and Counter	18 <u>53</u>	

General Observations and Opinion,

This vessel is in good order sufficient and in our opinion fit to remain as classed

The Amount of Fee.....£ : : is received by me, J. H. Ritchie

Special..... / : / : -

Certificate (if required) : :

Committee's Minute _____ 18 _____

Character assigned _____



© 2019

Lloyd's Register Foundation

LOV 635-0389