

REPORT of SURVEY for REPAIRS.

#10657
Change of Owner

No. Survey held at London Date 12 to 22 April 1854
on the Brig Sultana Master W Allen
Tonnage 181 Built at Yarmouth When built 1833
By whom built Owners J Williams
Port belonging to London Destined Voyage Trinidad
If Surveyed Afloat or in Dry Dock West India Dock

Last Survey, No. 19249 Port London

REPAIRS

Found the deck hook defective one of Iron Has been in
compensation applied under it Caulked from metal sheathing
upwards decks inclusive the latter are a good deal worn but
tight

Present Condition of the

Decks <u>Fair for class</u>	Treenails <u>Not seen</u>	Windlass and <u>Capstan</u>
Waterways } <u>Good</u>	Breasthooks and Stemson	Pumps
Comings } <u>Good</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings } <u>Good & Firm</u>	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <u>Firm</u>	Keelsons	Sails
Planksheers } <u>Good when seen</u>	Clamps and Shelves	Anchors No. of <u>2 B 15 2 Kedges</u>
Sheerstrakes } <u>Good when seen</u>	Ceiling	Cables <u>Good & sufficient</u>
Topsides } <u>Good when seen</u>	Rudder	Hawsers and Warps <u>8 6 5 Good</u>
Wales } <u>Good when seen</u>	Copper <u>Yel. Met</u> When put on <u>1852</u>	Standing & Running Rigging <u>good order</u>
Plank (Bottom) and Counter <u>D D</u>		

General Observations and Opinion,

This vessel is at present in efficient order where
seen & having lapsed from want of survey on her present character
may now be classed A1.

Thomas Alexander

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 185

Character assigned



© 2019

Lloyd's Register
Foundation

LOV 635 - 0548