

REPORT of SURVEY for REPAIRS.

19673

No. 53 Survey held at London Date 25th 24 April 1855
 on the B.R. James Gibb Master G. Hattit H. L. Appleton
 Tonnage 696 Built at Quebec When built 1847
 By whom built _____ Owners C. Walton N. Gibson
 Port belonging to London Destined Voyage Bombay Per M. Walton
 If Surveyed Afloat or in Dry Dock in Fletchers dock

Last Survey, No. 18841 Port London Classed 5 A. 1
SS 1852 5th Feb Cont 1852 24th 54

REPAIRS

at present bottom stripped caulked and
 resheathed with yellow metal on felt
 wales, topsides, and upper deck caulked
 new Mizzen mast shipped -

Present Condition of the

Decks <u>Caulked</u>	Treenails	Windlass and Capstan <u>Refitted</u>
Waterways <u>do</u>	Breasthooks and Stemson	Pumps <u>Sufficient</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame	<u>New Mizzen Mast</u>
Lower Deck Beams & Fastenings <u>firm</u>	Keelsons	Masts, Yards, &c.
Planksheers	Clamps and Shelves <u>Good</u>	Sails <u>Sufficient</u>
Sheerstrakes <u>Caulked</u>	Ceiling	Anchors No. of <u>do</u>
Topsides <u>Caulked</u>	Rudder	Cables <u>do</u>
Wales	Copper <u>Ym</u> When put on <u>April</u>	Hawsers and Warps <u>do</u>
Plank (Bottom) and Counter	185 <u>5</u>	Standing & Running Rigging <u>do</u>

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways

This vessel appears to be in good
 and efficient condition and fit to remain
 as Closed

The Amount of Fee.....£ / : : is received by me, J. H. H. H. H.

Special..... : :

Certificate (if required) : :

Committee's Minute 18th May 1855

Character assigned F. 1 LD



© 2019

Lloyd's Register
 Foundation

LOW635-05066