

REPORT of SURVEY for REPAIRS.

No. 19142 Survey held at London Date July 28th 26th 18 53
 on the Brig Africanus Master Light
 Tonnage 85 Built at Yarmouth When built 1838
 By whom built _____ Owners Forster & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Young & Co Dock

Last Survey, No. _____ Port _____ Classed 12A1 Cont 50 for 4

REPAIRS At the present time Yellow Metal stripped off and 6 Strakes of Planking from the light Water Mark downwards has been retrenched the upper piece of Stem being badly decayed and Starboard Knee head has been removed and renewed with English Oak. She has been hung in Shores, and resheathed with yellow Metal over Side.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of <u>Good Huffer</u>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y Metal</u> When put on <u>new</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, This Brig appears now to be in good Condition and in my opinion fit to retain her class

M. M. Intype

The Amount of Fee.....£ 1 : 0 : 0 is received by me,

Special.....£ 1 : 1 : 0

Certificate (if required) : :

Committee's Minute 19th June 1855

Character assigned _____



© 2019

Lloyd's Register
Foundation

LON636-0039