

# ANNUAL SURVEYS.

19786

No. 324 Survey held at London Date June 15 1855  
 on the Ship "Ellenborough" Master \_\_\_\_\_  
 Tonnage 153 Built at Newcastle When built 1842  
 By whom built \_\_\_\_\_ Owners Watson  
 Port belonging to London Destined Voyage Australia  
 If Surveyed Afloat or in Dry Dock Up Youngs Dry Dock

Last Survey, No. 19092 Port of London Classed Cont 54-4 A. 1.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>1854</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways

Now done, the Yellow Metal sheathing patched. She appears in good and efficient Condition. fit in my opinion to remain classed A. 1.

Committee's Minute

10th Decy 1855

Character assigned

Cont 4 A. 1

B. Weymouth

Certificate (if required)

No. 17 Survey held at London Date June 15 1855  
 on the Ship "Galriada" Master J. Scott  
 Tonnage 1303 Built at Quebec When built 1849  
 By whom built \_\_\_\_\_ Owners Grainier  
 Port belonging to Liverpool Destined Voyage Al Rayah  
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 12233 Port of Liverpool Classed 6 A. 1.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper on felt	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>Now new</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways

Now done the Yellow Metal sheathing renewed on felt bottom Caulked and part of the Lower deck bolts renewed. She now appears in good and efficient Condition fit in my opinion to remain classed A. 1.

Committee's Minute

10th Decy 1855

Character assigned

6 A. 1

record Y.M.L.D.

B. Weymouth

Certificate (if required)

LON636-0080